


HISTORICAL PHOTOGRAPHS


- A. View of "The Maples" from 16th Street; date unknown.
- B. Northeast corner of the house; August, 1910.
- C. South façade of house with view of outbuildings and barns; before 1915.
- D. Southwest corner of the house; about 1919.
- E. North elevation of new porch; August 21, 1941.
- F. Privy located behind house; late 1930's.
- G. North façade of gray barn (barn #2); date unknown.
- H. View of red (barn #3), gray (barn #2), and south (barn #1) barns from below hill in front of house; May 26, 1919.
- I. West elevation of gray (barn #2) and south (barn #1) barns with corn crib; September 10, 1940.
- J. View south to the fields and chicken coop from the west side of the rear porch.






40C




















PHOTOGRAPHS



View of the north façade of the house and barn roof from the fork in the driveway.



Northwest corner and west façade of the house. Kitchen wing is at the rear; screen porch at the front.



Northeast corner of the house with screen porch, viewed from the drive to the barn.



Northeast corner of the house and screen porch. Note the ice dams at the eaves and the mildew on the trim boards.



East façade of the house; note the ice dams at the eaves and the addition at the rear of the building.



The south façade of the house shows the addition cantilevered over the original kitchen wing. Also note the addition at the east side.



The west façade of the rear of the house shows the addition cantilevered over the original kitchen wing.




South wall of the original basement foundation. Note the cantilevered addition and mildewed soffit boards above the wall.



Interior of the house looking into the parlor and front hall from the dining room.



Interior of renovated kitchen wing. Fireplace was added at time of renovation and is not original.



View of the dining room from the parlor.



View down the stair from the top landing. Note the restored balustrade and newel post. Also note the bathroom addition that was added over the lower stair landing.



Interior view from the addition into the renovated kitchen wing. Note the carpet on the floor was custom patterned to match an earlier carpet in the house.




Renovated kitchen.



Deteriorating brick floor in basement.



Interior stone walls and brick floor of original basement.



East facade of the garage with the north entry elevation.




West facades of the gray barn in the foreground with the red barn beyond.




North and west facades of the barns with the red barn in the foreground and the gray barn beyond.



Southwest corner of the gray barn. Note foundation walls of the missing south barn and one of the silos.



South façade of the gray barn.




East façade of the gray barn.




Southwest corner of the red barn and the northwest corner of the gray barn.



North elevation of the gray barn showing the damage at grade of the center bay entry doors and the west bay.



West gable end of the gray barn showing the separation of materials.




Interior of the gray barn looking from the north entry to the east bay with stalls and loft above.




Interior of the gray barn, looking at the structure of the west gable end.



Interior of the gray barn, looking toward the roof where the ventilator was originally located.



Interior of the gray barn looking from the north entry to the damaged south wall and west bay.




Interior of the gray barn at the animal stalls in the east bay.



Foundation wall of the south barn and one of the silos.




West façade of the red barn.



South wall of the red barn looking west toward the house.



East façade of the red barn with the east façade of the gray barn in the background.



North wall of the red barn looking east.



West elevation entry ramp of the red barn.



Interior view of the red barn, looking east from the west entry. Note the gypsum board covered walls of the storage room along the south wall.



Storage room enclosure in the red barn along the south wall.



Framing of the red barn's roof viewed from the hatch.



West wall of the basement of the red barn. Note the organic growth on the stones.



South wall of the basement of the red barn.

The following “Scope of Work Documents for Exterior Restorations to Van Raalte House” was written by J. Andrew Baer, Architect prior to the completion of this Historic Structures Report. The document is still in draft form and has never been released to the public for bids. It is included herein for reference only. Recommendations made by J. Andrew Baer Architect do not reflect the recommendations made by DeStigter/Smith Architects. DeStigter/Smith Architects does not accept any liability or responsibility for work contributed by other architects and contained herein for reference only.